

Oil Field Environmental Incident Summary

Incident: 20141020131627 **Date/Time of Notice:** 10/20/2014 13:16

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: VANVILLE 6-25H

Field Name: THOMPSON LAKE

Well File #: 18862

Date Incident: 10/19/2014 **Time Incident:** 11:30

Facility ID Number:

County: BURKE

Twp: 159

Rng: 91

Sec: 25

Qtr:

Location Description:

Submitted By: Danielle Dupay

Received By:

Contact Person: Danielle Dupay
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

| | Spilled | Units | Recovered | Units | Followup | Units |
|-------|---------|---------|-----------|---------|----------|---------|
| Oil | | | | | | |
| Brine | 2 | Barrels | 2 | Barrels | 2 | barrels |
| Other | | | | | | |

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/4/2016

Clean Up Concluded: 10/20/2014

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Liquids were removed using vac truck the vic has been replaced and cleanup crew was called to removed contaminated material inside treater building.

Wastes Disposal Location: The Solids will be taken Clean Harbors, the liquids to an SWD.

Agencies Involved:

Updates

Date: 10/27/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak, remained on location within the diking according to the report. NDIC retains oversight.